

## Type of Change

Redesign – Querx sensor cap

## Affected Products

Product	Item number	Old version	New version
Querx TH	EGN600214	1.1	1.2
Querx WLAN TH	EGN601215	1.1	1.2

## Description of Change

The sensor cap for Querx TH and Querx WLAN TH has been changed in the following ways:

The slot in the sensor cap has been reduced from 1.4 mm to 1.1 mm, as the sensor is now sourced from a different manufacturer.

The item number has not changed. The devices are identified by the type plate.

## Impact of Change

Reduces the tolerances of measurements within a production lot.

## Contact

If you have questions concerning this product change, please contact us at [info@egnite.de](mailto:info@egnite.de).