

# Type of Change

Redesign – Querx sensor cap

### Affected Products

Product	ltem number	Old version	New version
Querx TH	EGN600214	1.0	1.1
Querx WLAN TH	EGN601215	1.0	1.1

### **Description of Change**

The sensor cap for Querx TH and Querx WLAN TH has been changed in the following ways:

The two halves of the cap are now fixed by screws, instead of being glued.

A magnet has been added to the cap, in order to make it possible to fix it to surfaces that contain iron, nickel or cobalt.

The cap's dimensions have changed from  $1.3 \times 0.5 \times 0.2$  ins to  $1.5 \times 0.4 \times 0.2$  ins (L x W x H).

The item number has not changed. The devices are identified by the type plate.

## Impact of Change

The new sensor cap makes it easier to replace the temperature/humidity sensor.

The sensor can be fixed to metal surfaces.

#### Contact

If you have questions concerning this product change notification, please contact us at info@egnite.de.

PCN number 20181001 | PCN date 20.10.18 egnite GmbH | Erinstrasse 18 | 44575 Castrop-Rauxel | Germany